

**SAS Superstructure**

Location: 04-SF-80-13.2 / 13.9

Client Name: CalTrans

Run date 22-Nov-14

Time 9:31 AM

**Daily Diary Report by Bid Item**

Contract No.: 04-0120F4

Diary #: 188 Const Calendar Day: 282 Date: 13-Mar-2013 Wednesday

Inspector Name: Liu, Tai-Lin Title: Transportation Engineer

Inspection Type: Continuous

Shift Hours: 07:00 AM 04:00 PM Break: 00:30 Over Time:

Federal ID:

Location:

Reviewer: Soheilifard, Saman Approved Date: Status: Submit

**04-0120F4  
04-SF-80-13.2/13.9  
Self-Anchored  
Suspension Bridge****Weather**

Temperature 7 AM 47 12 PM 70 4PM 68

Precipitation Condition Clear

Working Day ☒ If no, explain:**Diary:**

Dispute

**Paint Cable System**

03-13-13, Wednesday, Clear, 46-74 F - Cable Suspender Rope Paint (North/South Main Span)

- Arrived office around 07:15.
- Alex talked to me for helping him to measure N/S 104 & 106 CB bolt elongation.
- Talked to Saman, Laraine & Mahmoud and informed them I can not work paint inspection today.
- Went to field around 08:30 AM with Alex & John also Laraine as well at east end area.
- Measurement ended around 11:25 AM.
- Went back office starting processing measurement data measured on yesterday (W2) & N/S 104 & 106 CB bolts.
- There was bolting ID problem, went back to field to verify the ID with John at afternoon.
- Informed Mahmoud that I can not do paint inspection today and will be job site tomorrow morning for paint work.
- Continued performing bolt elongation data processing until 04:10 PM.
- Left office around 4:15 PM.
- No OT for today (3/13/13).

